

---

ANNEX P: List of Structures Impacted within the ETP Footprint



A handwritten signature in black ink, appearing to be "Rajendra".





## Annex P

List of affected households/Structures within the Project Footprint

S. No.	Segment	Location of Structure	Structure
1	IB-NB	Nawalparashi, Sunwal 13	12
2	NB-ND	Palpa, Nisdi 7	4
3	NB-ND	Palpa, Nisdi 6	3
4	NB-ND	Palpa, Nisdi 5	3
5	NB-ND	Palpa, Rampur 1	1
6	NB-ND	Tanahu, Ghiring 1	6
7	NB-ND	Tanahu, Ghiring 3	3
8	NB-ND	Tanahu, Ghiring 5	6
9	NB-ND	Tanahu, Ghiring 6	2
10	NB-ND	Tanahu, Rishing 8	2
11	NB-ND	Tanahu, Rishing 1	3
12	ND-RTE	Tanahu, Abukhaireni 4	3
13	ND-RTE	Chitwan, Icchakamana 6	2
14	ND-RTE	Dhading, Benighatrorang 10	9
15	ND-RTE	Dhading, Gajuri 2	6
16	ND-RTE	Dhading, Siddhalekh 6	2
17	ND-RTE	Dhading, Galchi 2	4
18	ND-RTE	Nuwakot, Tarkeshwar 2	2
19	ND-RTE	Nuwakot, Belkotgadhi 7	5
20	RTE-Lap	Nuwakot, Belkotgadhi 7	8
21	RTE-Lap	Nuwakot, Belkotgadhi 8	2
22	RTE-Lap	Nuwakot, Belkotgadhi 10	4
23	RTE-Lap	Nuwakot, Belkotgadhi 12	7
24	RTE-Lap	Nuwakot, Likhu 5	4
25	RTE-Lap	Nuwakot, Likhu 6	3
26	RTE-Lap	Nuwakot, Shivapuri 8	3
27	RTE-Lap	Nuwakot, Panchakanya 5	6
28	RTE-Lap	Nuwakot, Shivapuri 3	3
29	RTE-Lap	Nuwakot, Shivapuri 4	3
30	RTE-Lap	Sindhupalchowk, Melamchi 4	9
31	RTE-Lap	Sindhupalchowk, Melamchi 1	3
32	RTE-Lap	Kathmandu, Shankharapur 2	2
33	RTE-NH	Nuwakot, Belkotgadhi 7	5
34	RTE-NH	Nuwakot, Belkotgadhi 5	8



S. No.	Segment	Location of Structure	Structure
35	RTE-NH	Dhading, Galchi 8	5
36	RTE-NH	Dhading, Thakre 11	1
37	RTE-NH	Dhading, Thakre 3	3
38	RTE-NH	Makawanpur, Thaha 8	13
39	RTE-NH	Makawanpur, Kailash 6	4
40	RTE-NH	Makawanpur, Kailash 4	5
41	RTE-NH	Makawanpur, Hetauda 19	7
42	RTE-NH	Makawanpur, Hetauda 11	15
43	Ratmatae SS	Nuwakot, Belkotgadhi 7	104
<b>Total</b>			<b>305</b>

Note:

- IB = India Border, NB = New Butwal, ND = New Damauli, RTE = Ratmatae, Lap = Lapsipedi, NH = New Hetuda & SS = Substation;
- Others means Cow shed, goat shed, monkey shed, ruined structures, toilet and other associated structures
- Abovementioned structures belongs to 187 households.
- This data was extracted from LiDAR imagery and ground verified by Community Liaison Officers



*Signature*

